

---

## Bucket Testing Services

All irrigation systems **must be tested every three years**. ALIL can help with bucket testing on farm. Our services include bucket testing all irrigation systems.

ALIL bucket testing costs include:

### **Pivots & Laterals**

Up to 9 Spans - \$150 per irrigator

10 Spans or more - \$175 per irrigator

Corner Arm - \$25 (Additional charge)

### **Other**

Hard Hose Guns, Rotary, Linear Booms & Effluent Spreader - \$175 per irrigator

K-Lines - \$5 per pod, minimum - \$50

---

**ALIL Office: 326 Burnett Street, Email: [info@alil.co.nz](mailto:info@alil.co.nz)**

**Website: [www.alil.co.nz](http://www.alil.co.nz)**